Division of Health Care Facilities

PAGE 21/21 PRINTED: 08/19/2010 FORM APPROVED

(X3) DATE SURVEY

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A BUILDING 01 - MAIN BUILDING 01		(X3) DATE SURVEY COMPLETED	
		TN7566		B. WING _		08/1	17/2010
202			202 EAS	ET ADDRESS, CITY, STATE, ZIP CODE EAST MTCS ROAD FREESBORO, TN 37138			
(X4) ID PREFIX TAG	SUMMARY ST. (EACH DEFICIENC REGULATORY OR I	FULL	PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(XS) COMPLETE DATE	
N 831	1200-8-608(1) Bu		N 831	N 831			
Division/df He	(1) The nursing home must be constructed, arranged and maintained to ensure the safety of the resident.  This Rule is not met as evidenced by: Based on observations it was determined the facility failed to maintain the physical environment.  The findings include:  1. Observation of residents' room 315 on 8/17/10, at 5:55 p.m., revealed the ceiling tile located above the window had mold and water damage. Tennessee department of Health (TDOH) 1200-8-6,-08(1)  2. Observation of the conference room on 8/17/10, at 5:59 p.m., revealed the ceiling tile located above the room door had mold and water damage. TDOH 1200-8-6,-08(1)  These findings were acknowledged by the Administrator and verified by the Maintenance Director at the exit interview on 8/17/10.				the maintenance supervisor on 8/19/16. The ceiling tile in the conference replaced by the maintenance supervisor made rounds on 8/19/10 to ensure that ceil not contain water or mold spots.  3. The administrator in-serviced the supervisor on 8/19/10 on maintaining physical environment of the facility.  4. The maintenance supervisor will compliance during daily facility rour report findings to the Committee cor Medical Director, Administrator, DC MDS Coordinator, Risk Menagement	by failed to maintain the physical nt.  ve Action  ceiling tile in room 315 was replaced by enance supervisor on 8/19/10.  diling tile in the conference room was ny the maintenance supervisor on aintenance supervisor on aintenance supervisor made facility 18/19/10 to ensure that ceiling tiles did in water or mold spots.  Immistrator in-serviced the maintenance or on 8/19/10 on maintaining the environment of the facility maintenance supervisor will monitor for one during daily facility rounds and will dings to the Committee consisting of Director, Administrator, DON, ADON, ordinator, Risk Management, ping, Payroll, Social Services, Activities, vice Supervisor, Maintenance and	
LABORATORY	Palth Care Facilities  OUT OF PROVIDENCE OF	DENSUPPLIER REPRESEI	TATIVE'S SIG	SNATURE	Odninista.	for 9	(X5) DATE -3-/©